

TEST REPORT

Client: Supacolor
12705 Daphne Ave.
Hawthorne, CA 90250
Attention: Star Diaz
E-Mail: star@supacolor.com

Sample Description as Declared :

Sample Description: Wearable transfer
Color: Black
Style # : Not Provided
Fabric/Garment Weight: Not Provided
Fiber Content: 100% Cotton
No. of Samples: 2
End Use: Not Provided
Care Instructions: Per Label: Machine Wash Cold with like colors. Only non-chlorine bleach when needed. Tumble dry Low. Warm iron if necessary.
Sample Received Date: January 24, 2024
Final Confirmation Date: January 30, 2024
Test Period: January 30, 2024, February 16, 2024

OVERALL CONCLUSION:

Standard
AATCC TS-008 – Appearance of Apparel and Other Textile Products After Laundering

Result
See Results



For and on behalf of Intertek:

Edwin Serrano

Intertek

545 E Algonquin Road, Suite H
Arlington Heights, Illinois 60005, USA
Telephone: 847-871-1020 Fax: 847-439-6156



Test Performed As Requested by Client:

TEST RESULTS:

1. AATCC TS-008 – Appearance of Apparel and Other Textile Products After Laundering

Sample Description: Black Wearable Transfer
After 10 Washes

Washing Conditions: Machine Wash (AATCC) Cold at 80°F, Normal Cycle, Tumble Dry Low, AATCC W/Brightener, 4.0 lbs wash Load, AATCC Type 3 Ballast (50% Cotton/50% Polyester).

Appearance Change Results:

Color Change:	Grade:
Color Change – Fabric (Requirement: 3.5)	-
Color Change – Print (if applicable) (Requirement: 3.5)	4.5
Color Change – Appliqués/Trims/Linings (if applicable) (Requirement: 3.5)	-
Self/Cross Staining (if applicable) (Requirement: 4.5)	4.5

Multifiber Used: No. 10

Color Staining: (Requirement: 4.0)	Grade:
Acetate Staining	4.5
Cotton Staining	4.5
Nylon Staining	4.5
Polyester/Silk Staining	4.5
Acrylic/Viscose Rayon Staining	4.5
Wool Staining	4.5

Visual Evaluation:	Grade:
Hand Feel	Negligible
Abrasion Marks	Negligible

Other Visual Evaluation:	
Delamination/Peeling	Satisfactory
Embellishment Cracking	Satisfactory
Embellishment Puckering	Satisfactory

Intertek

545 E Algonquin Road, Suite H
Arlington Heights, Illinois 60005, USA
Telephone: 847-871-1020 Fax: 847-439-6156



AATCC TS-008 – Appearance of Apparel and Other Textile Products After Laundering

Sample Description: Black Wearable Transfer

After 20 Washes

Washing Conditions: Machine Wash (AATCC) Cold at 80°F, Normal Cycle, Tumble Dry Low, AATCC W/Brightener, 4.0 lbs wash Load, AATCC Type 3 Ballast (50% Cotton/50% Polyester).

Appearance Change Results:

Color Change:	Grade:
Color Change – Fabric (Requirement: 3.5)	-
Color Change – Print (if applicable) (Requirement: 3.5)	4.5
Color Change – Appliqués/Trims/Linings (if applicable) (Requirement: 3.5)	-
Self/Cross Staining (if applicable) (Requirement: 4.5)	4.5

Visual Evaluation:	Grade:
Hand Feel	Negligible
Abrasion Marks	Negligible

Other Visual Evaluation:	
Delamination/Peeling	Satisfactory
Embellishment Cracking	Satisfactory
Embellishment Puckering	Satisfactory



AATCC TS-008 – Appearance of Apparel and Other Textile Products After Laundering

Sample Description: Black Wearable Transfer

After 30 Washes

Washing Conditions: Machine Wash (AATCC) Cold at 80°F, Normal Cycle, Tumble Dry Low, AATCC W/Brightener, 4.0 lbs wash Load, AATCC Type 3 Ballast (50% Cotton/50% Polyester).

Appearance Change Results:

Color Change:	Grade:
Color Change – Fabric (Requirement: 3.5)	-
Color Change – Print (if applicable) (Requirement: 3.5)	4.5
Color Change – Appliqués/Trims/Linings (if applicable) (Requirement: 3.5)	-
Self/Cross Staining (if applicable) (Requirement: 4.5)	4.5

Visual Evaluation:	Grade:
Hand Feel	Negligible
Abrasion Marks	Negligible

Other Visual Evaluation:	
Delamination/Peeling	Satisfactory
Embellishment Cracking	Satisfactory
Embellishment Puckering	Satisfactory



AATCC TS-008 – Appearance of Apparel and Other Textile Products After Laundering

Sample Description: Black Wearable Transfer

After 40 Washes

Select Washing Type

Washing Conditions: Machine Wash (AATCC) Cold at 80°F, Normal Cycle, Tumble Dry Low, AATCC W/Brightener, 4.0 lbs wash Load, AATCC Type 3 Ballast (50% Cotton/50% Polyester).

Appearance Change Results:

Color Change:	Grade:
Color Change – Fabric (Requirement: 3.5)	-
Color Change – Print (if applicable) (Requirement: 3.5)	4.5
Color Change – Appliqués/Trims/Linings (if applicable) (Requirement: 3.5)	-
Self/Cross Staining (if applicable) (Requirement: 4.5)	4.5

Visual Evaluation:	Grade:
Hand Feel	Negligible
Abrasion Marks	Negligible

Other Visual Evaluation:	
Delamination/Peeling	Satisfactory
Embellishment Cracking	Satisfactory
Embellishment Puckering	Satisfactory



AATCC TS-008 – Appearance of Apparel and Other Textile Products After Laundering

Sample Description: Black Wearable Transfer

After 50 Washes

Washing Conditions: Machine Wash (AATCC) Cold at 80°F, Normal Cycle, Tumble Dry Low, AATCC W/Brightener, 4.0 lbs wash Load, AATCC Type 3 Ballast (50% Cotton/50% Polyester).

Appearance Change Results:

Color Change:	Grade:
Color Change – Fabric (Requirement: 3.5)	-
Color Change – Print (if applicable) (Requirement: 3.5)	4.5
Color Change – Appliqués/Trims/Linings (if applicable) (Requirement: 3.5)	-
Self/Cross Staining (if applicable) (Requirement: 4.5)	4.5

Visual Evaluation:	Grade:
Hand Feel	Negligible
Abrasion Marks	Negligible

Other Visual Evaluation:	
Delamination/Peeling	Satisfactory
Embellishment Cracking	Satisfactory
Embellishment Puckering	Satisfactory

Additional Comments: Slight Print Puckering Observed.



AATCC TS-008 – Appearance of Apparel and Other Textile Products After Laundering

Sample Description: Black Wearable Transfer

After 60 Washes

Washing Conditions: Machine Wash (AATCC) Cold at 80°F, Normal Cycle, Tumble Dry Low, AATCC W/Brightener, 4.0 lbs wash Load, AATCC Type 3 Ballast (50% Cotton/50% Polyester).

Appearance Change Results:

Color Change:	Grade:
Color Change – Fabric (Requirement: 3.5)	-
Color Change – Print (if applicable) (Requirement: 3.5)	4.5
Color Change – Appliqués/Trims/Linings (if applicable) (Requirement: 3.5)	-
Self/Cross Staining (if applicable) (Requirement: 4.5)	4.5

Visual Evaluation:	Grade:
Hand Feel	Negligible
Abrasion Marks	Negligible

Other Visual Evaluation:	
Delamination/Peeling	Satisfactory
Embellishment Cracking	Satisfactory
Embellishment Puckering	Satisfactory



AATCC TS-008 – Appearance of Apparel and Other Textile Products After Laundering

Sample Description: Black Wearable Transfer

After 70 Washes

Washing Conditions: Machine Wash (AATCC) Cold at 80°F, Normal Cycle, Tumble Dry Low, AATCC W/Brightener, 4.0 lbs wash Load, AATCC Type 3 Ballast (50% Cotton/50% Polyester).

Appearance Change Results:

Color Change:	Grade:
Color Change – Fabric (Requirement: 3.5)	-
Color Change – Print (if applicable) (Requirement: 3.5)	4.5 (Slight wash off of Pink print)
Color Change – Appliqués/Trims/Linings (if applicable) (Requirement: 3.5)	-
Self/Cross Staining (if applicable) (Requirement: 4.5)	4.5

Visual Evaluation:	Grade:
Hand Feel	Negligible
Abrasion Marks	Negligible

Other Visual Evaluation:	
Delamination/Peeling	Satisfactory
Embellishment Cracking	Satisfactory
Embellishment Puckering	Satisfactory

Additional Comments: Slight Puckering of print observed



AATCC TS-008 – Appearance of Apparel and Other Textile Products After Laundering

Sample Description: Black Wearable Transfer

After 80 Washes

Washing Conditions: Machine Wash (AATCC) Cold at 80°F, Normal Cycle, Tumble Dry Low, AATCC W/Brightener, 4.0 lbs wash Load, AATCC Type 3 Ballast (50% Cotton/50% Polyester).

Appearance Change Results:

Color Change:	Grade:
Color Change – Fabric (Requirement: 3.5)	-
Color Change – Print (if applicable) (Requirement: 3.5)	4.5 (Slight wash off of pink observed)
Color Change – Appliqués/Trims/Linings (if applicable) (Requirement: 3.5)	-
Self/Cross Staining (if applicable) (Requirement: 4.5)	4.5

Visual Evaluation:	Grade:
Hand Feel	Negligible
Abrasion Marks	Negligible

Other Visual Evaluation:	
Delamination/Peeling	Satisfactory
Embellishment Cracking	Satisfactory
Embellishment Puckering	Satisfactory

Additional Comments: Slight puckering of print observed



57217 AFTER 10HL	57217 AFTER 20HL	57217 AFTER 30HL
 <p>Supacolor. We help you make it. Supacolor. We help you make it.</p> <p>AFTER 10HL Original 57217</p>	 <p>Supacolor. We help you make it. Supacolor. We help you make it.</p> <p>AFTER 20HL Original 57217</p>	 <p>Supacolor. We help you make it. Supacolor. We help you make it.</p> <p>AFTER 30HL Original 57217</p>
57217 AFTER 40HL	57217 AFTER 50HL	57217 AFTER 50HL
 <p>Supacolor. We help you make it. Supacolor. We help you make it.</p> <p>AFTER 40HL Original 57217</p>		 <p>Supacolor. We help you make it. Supacolor. We help you make it.</p> <p>AFTER 50 Original 57217</p>

Intertek

545 E Algonquin Road, Suite H
Arlington Heights, Illinois 60005, USA
Telephone: 847-871-1020 Fax: 847-439-6156



<p>57217 AFTER 60HL</p> 	<p>57217 AFTER 60HL</p> 	
<p>57217 AFTER 70HL</p> 	<p>57217 AFTER 70HL</p> 	<p>57217 AFTER 70HL</p> 

Intertek

545 E Algonquin Road, Suite H
Arlington Heights, Illinois 60005, USA
Telephone: 847-871-1020 Fax: 847-439-6156





The test results stated in this report relate only to the item(s) tested. This test report may not be reproduced except in full, without written approval of Intertek.



*If you need assistance in interpreting these results or if you have any questions,
please feel free to call Customer Service Department*

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or willful misconduct.

Intertek

545 E Algonquin Road, Suite H
Arlington Heights, Illinois 60005, USA
Telephone: 847-871-1020 Fax: 847-439-6156

